



To: n-30-1-87728- Design Quality Assurance Bureau EIS Administrator Bldg. 5, Rm. 408 MC 0750,		New York State Department of Transportation ENGINEERING BULLETIN	EB 97-065
<i>Expires one year after issue unless replaced sooner</i>			

Title: **Superseding Outdated Engineering Instructions**

Distribution: <input checked="" type="checkbox"/> Manufacturers (18) <input checked="" type="checkbox"/> Surveyors (33) <input checked="" type="checkbox"/> Main Office (30) <input checked="" type="checkbox"/> Consultants (34) <input checked="" type="checkbox"/> Local Govt. (31) <input checked="" type="checkbox"/> Contractors (39) <input checked="" type="checkbox"/> Regions/Agencies (32) <input type="checkbox"/> _____ ()	Approved:  Kenneth C. Hahn, EIS Administrator <u>12/31/97</u> Date
--	--

Throughout the previous year it was brought to our attention that certain Engineering Instructions listed in our database as current are obsolete or contain minor errors. They have been superseded by other issuances, contain outdated or otherwise incorrect material, were omitted from lists of EIs superseded by other issuances, or were overlooked when they were superseded by other issuances. Changes are effective immediately. The 16 Engineering Instructions identified at this time are:

1. EI 85-047 *"Signal Controllers"*
 Per Design Quality Assurance Bureau: EI 85-047 disapproved the listed items. EI 85-047 is obsolete and will be shown as: Superseded by EB97-065.

2. EI 86-009 *"Planting Details Standard Sheet"*
 Per DQAB: The attached standard sheet was included in EB 86-007, "Standard Sheet Index" and the information contained in EI 86-009 was later included in Addendum No.2 to the Standard Specifications of 1985. EI 86-009 will be shown as: Superseded by Addendum # 2 Standard Specifications of January 2, 1985 effective June 2, 1988.

3. EI 88-016 *"615-Standard Sheets"*
 Per Landscape Architecture Bureau: EI 88-016 disapproved the listed items and the related standard sheets. EI 88-016 is obsolete and will be shown as: Superseded by EB 97-065.

4. EI 88-023 *"Insurance"*
 Per DQAB: The information was later included in the Standard Specifications of 1990. EI 88-023 will be shown as: Superseded by the NYSDOT Standard Specifications of January 2, 1990.

5. EI 90-010 *"Specification for Bridge Construction Items 16555.5005 and 16555.5505"*
 Per DQAB: Correct all copies of EI 90-010 to read Supersedes EI 89-026 from Supersedes EI 87-032. EI 89-026 had previously superseded EI 87-032.

6. EI 91-013 *"Section 610-Turf and Wildflower Establishment Revisions"*
 Per LAB: The information was later included in Addendum No. 1 to the Standard Specifications of 1990. EI 91-013 will be shown as: Superseded by Addendum #1 to the NYSDOT Standard Specifications of January 2, 1990, effective November 18, 1993.

7. EI 92-013 *"Revisions to Sections 612, 614 and 713 of the Standard Specifications of January 2, 1990"*
 Per LAB: The information was later included in Addendum No. 1 to the Standard Specifications of 1990. EI 92-013 will be shown as: Superseded by Addendum #1 to the NYSDOT Standard Specifications of January 2, 1990, effective November 18, 1993.

EB 97-065 Page 2 of 2

8. EI 92-034 "*Asbestos*"
Per Environmental Analysis Bureau: The specifications issued were replaced by the specifications included in EI 96-026. The remainder of the material was replaced by a revised chapter 1.3 issued by EB 96-035. EI 92-034 will be shown as: Superseded by EB 96-035.
9. EI 92-045 "*Asbestos*"
Per EAB: The specifications issued were replaced by the specifications included in EI 96-026. The remainder of the material was replaced by a revised chapter 1.3 issued by EB 96-035. EI 92-045 will be shown as: Superseded by EB 96-035.
10. EI 93-002 "*Asbestos Blanket Variance 6R1*"
Per EAB: The specifications issued were replaced by the specifications included in EI 96-026. The remainder of the material was replaced by a revised chapter 1.3 issued by EB 96-035. EI 93-002 will be shown as: Superseded by EB 96-035.
11. EI 93-007 "*Addendum Number 1 to the Standard Specifications of January 2, 1990*"
Per DQAB: This EI announced the issuance of the Addendum and included a short description of some of the contents. EI 93-007 is obsolete and will be shown as: Superseded by EB 97-065.
12. EI 94-013 "*Required Regional Use of Recycled Tire Rubber in Hot Mix Asphalt for Federal Fiscal Year 1995*"
Per DQAB: The requirement was for one federal fiscal year, specifically from October 1994 through September 1995. The U.S. Congress passed a temporary moratorium against enforcing the requirement in the next year; in subsequent ISTEAs the requirement was not renewed. EI 94-013 will be shown as: Superseded by EB 97-065.
13. EI 94-027 "*Asbestos Removal Blanket Variance 3- (revision 1)*"
Per EAB: The specifications issued were replaced by the specifications included in EI 96-026. The remainder of the material was replaced by a revised chapter 1.3 issued by EB 96-035. EI 94-027 will be shown as: Superseded by EB 96-035.
14. EI 95-018 "*Surveying Standards and Procedures Manual*"
Per Design Services Bureau: This EI announced the issuance of the noted Surveying Manual. Amendments to the manual were distributed with EB 96-010. EI 95-018 is obsolete and will be shown as: Superseded by EB 96-010.
15. EI 95-030 "*Distribution of BDD 89-59A & BDD 89-59B- Design Criteria for Bridges*"
Per DQAB: Correct the first sentence of all copies of EI 95-030 to read ". . . supersedes EI 89-002 . . ." from ". . . supersedes EI 82-002 . . ." For your information, EI 82-002 has been superseded by EB 97-006.
16. EI 95-039 "*Approved List Distribution*"
Per Materials Bureau: This EI announced the annual issuance of the Approved List for Materials and Equipment (previously it was semiannual). The change will continue in effect, however, the EI is obsolete. EI 95-039 will be shown as: Superseded by EB 97-065.

Note: EB 97-001, on page 5, at the reference to EB 96-013. The mail lists should include list 39(Manufacturers) but not list 34(Consultants). Please correct all copies of EB97-001.

Questions regarding this Engineering Bulletin should be directed to Lois Groskopf in the Design Quality Assurance Bureau at [518] 457-5597.