


TO: SUPERSEDED BY EI 82-005 EFFECTIVE 3/15/82	ENGINEERING INSTRUCTION	
	NEW YORK STATE DEPARTMENT OF TRANSPORTATION	
	SUBJECT: STANDARD DETAILS FOR HIGHWAY BRIDGE REVISIONS TO	
	Subject Code: 7.35-11	
Distribution:	<input type="checkbox"/> Main Office <input type="checkbox"/> Regions <input checked="" type="checkbox"/> Special	Code: <u>EI-81-7</u>
APPROVED:	 <u>E.V. MOURIGAN, Deputy Chief Engineer (Structures)</u>	Date: <u>JAN. 8, 1981</u> Supersedes: EI 74-113 & EI 79-002

Attached are the following GLD's

GLD-A2 dated 11/80 previously issued by EI 79-50 dated 11/16/79
 GLD-A3 dated 11/80 previously issued by EI 79-50 dated 11/16/79
 GLD-A6 dated 11/80 previously issued by EI 79-50 dated 11/16/79
 GLD-A7 dated 11/80 previously issued by EI 79-50 dated 11/16/79
 GLD-A9 dated 11/80 previously issued by EI 79-50 dated 11/16/79
 GLD-A11 dated 11/80 previously issued by EI 79-50 dated 11/16/79
 GLD-A13 dated 11/80 previously issued by EB 9-8 dated 3/22/79
 GLD-A14 dated 11/80 previously issued by EB 9-8 dated 3/22/79
 GLD-A15 dated 11/80 previously issued by EB 9-8 dated 3/22/79
 GLD-MC1 dated 11/80 previously issued by EB 9-8 dated 3/22/79
 GLD-MC2 dated 11/80 previously issued by EI 74-113 dated 1/2 /75
 GLD-MC3 dated 11/80 previously issued by EI 79-2 dated 1/10/79
 GLD-PC1 dated 11/80 previously issued by EI 79-50 dated 11/16/79
 GLD-PC2 dated 11/80 previously issued by EI 79-50 dated 11/16/79
 GLD-PC5 dated 11/80 previously issued by EI 76-52 dated 7/16/76
 GLD-PC6 dated 11/80 previously issued by EI 76-52 dated 7/16/76
 GLD-PC8 dated 11/80 previously issued by EB 9-8 dated 3/22/79
 GLD-PC10 dated 11/80 previously issued by EI 76-52 dated 7/16/76
 GLD-S1 dated 11/80 previously issued by EB 9-8 dated 3/22/79
 GLD-S2 dated 11/80 previously issued by EI 76-52 dated 7/16/76
 GLD-S3 dated 11/80 previously issued by EI 76-52 dated 7/16/76
 GLD-S4 dated 11/80 previously issued by EI 79-50 dated 11/16/79

The following are the list of changes and/or additions to the GLD's

GLD-A2 Location of Epoxy Coated bars
 GLD-A3 Location of Epoxy Coated bars
 GLD-A6 Location of Epoxy Coated bars
 GLD-A7 Location of Epoxy Coated bars
 GLD-A9 Location of Epoxy Coated bars
 GLD-A11 Location of Epoxy Coated bars
 GLD-A13 Location of Epoxy Coated bars
 GLD-A14 Location of Epoxy Coated bars
 GLD-A15 Location of Epoxy Coated bars
 GLD-MC1 Location of Epoxy Coated bars
 GLD-MC2 Minor corrections and note on Epoxy Coated bars

Subject: STANDARD DETAILS FOR HIGHWAY BRIDGE REVISIONS TO

GLD-MC3 Noted M & N changed
GLD-PC1 Mortar pad note changed
GLD-PC2 Slab concrete Type "A" changed to Type "E"
Note on Epoxy Coated bars
GLD-PC5 Minor corrections, and hole in bearing changed to 2"
GLD-PC6 Pay limits for slab added and Anchor bar hole
changed to 2"
GLD-PC8 Epoxy Coated bars in slab noted
GLD-PC10 "Welded Bar Connection changed from 1" Min. to
1/4 bar dia. or 3/16" Max.
GLD-S1 Epoxy Coated bars in Slab labeled
GLD-S2 Epoxy Coated bars in Slab labeled
GLD-S3 Epoxy Coated bars in Slab labeled
GLD-S4 Epoxy Coated bars in Slab labeled and
Spacing of chamfer in parapet changed

EI 79-50 Still in effect
EB 9-8 Has expired
EI 74-113 Superseded by this EI
EI 79-2 Superseded by this EI
EI 76-52 Still in effect