


TO: SUPERSEDED BY EB 99-025 EFFECTIVE 3/17/99	<h1>ENGINEERING INSTRUCTION</h1> <p>NEW YORK STATE DEPARTMENT OF TRANSPORTATION</p>
Distribution: 31 <input checked="" type="checkbox"/> Main Office 33 <input checked="" type="checkbox"/> Regions 34 <input checked="" type="checkbox"/> Special	Code: <u>E.I. 86-30</u> Date: <u>Sept. 2, 1986</u> Supersedes:
APPROVED:  Deputy Chief Engineer (Structures)	

According to the latest listing of available construction items, there are nine items concerned with the repair of non-working cracks. All of these items require the use of either a low-viscosity injected epoxy system, or an epoxy paste to achieve their purpose.

The current listing of these items is:

- 11555.8001 - Type 1 Crack Repair
- 11555.8002 - Type 2 Crack Repair
- 11555.8004 - Type 1 Crack Repair
- 11555.8005 - Crack Repair Type 1
- 11555.8006 - Type 1 Crack Repair
- 11555.8010 - Type 2 Crack Repair
- 08555.8002 - Crack Repair - Epoxy Paste
- 10555.8020 - Repair of Cracks 1/8" - 1/4"
- 10555.8025 - Repair of Cracks over 1/4" to 1" wide
- 08555.8001 - Type 1 Crack Repair
- 09555.8001 - Type 1 Crack Repair
- 09555.8002 - Type 2 Crack Repair
- 11555.94 - Furnishing Epoxy Injection Equipment
- 11555.9402 - Repair of Stone Masonry...Cracks Wider Than 1/4 Inch
- 11555.9402 - Repair of Stone Masonry...Cracks Narrower Than 1/4 Inch
- 11555.3601 - Epoxy Repair of Floor Beams

We have been informed by the Materials Bureau that proper use of the materials required by the foregoing items, necessitates a field inspection and subsequent approval by their office. Contact the General Engineering Section at (518) 457-4285 to arrange for field inspections.

Therefore, beginning immediately, this office will accept for review and processing, items of the foregoing type only if they are accompanied by a Materials Bureau approval memorandum for the project in question. All such items lacking an approval memorandum will be disallowed and returned unreviewed and unapproved.