


JAN 18 1974
D.O. File

TO: Director, Preliminary Plan Review Bureau SUPERSEDED BY EB 99-014 EFFECTIVE 2/23/1999	ENGINEERING INSTRUCTION NEW YORK STATE DEPARTMENT OF TRANSPORTATION SUBJECT: EI 74-2, STANDARD SHEET 645-8R1 Subject Code: 7.27-2-645
Distribution: <input checked="" type="checkbox"/> Main Office <input checked="" type="checkbox"/> Regions <input type="checkbox"/> Special	Code: <u>74-7</u> Date: <u>1/14/74</u>
APPROVED:  <u>Deputy Chief Engineer, Facilities Design Subdivision</u>	Modifies: EI 74-002 DATE 1/2/1974

Engineering Instruction 74-2, Standard Sheet 645-8R1, Standard Regulatory and Warning Signs gave four new pay items for three sizes of five sided school signs and a no passing pennant sign. These new pay items were inadvertently assigned pay item numbers already in use. For this reason, wherever the following pay item numbers appear in EI 74-2 and its accompanying sketch they should be changed as shown below:

<u>WRONG</u> <u>ITEM NO.</u>	<u>ITEM</u>	<u>CORRECT</u> <u>ITEM NO.</u>
645.2610	Traffic Sign, Five Sided, 30 Inch	645.2910
645.2620	Traffic Sign, Five Sided, 36 Inch	645.2920
645.2630	Traffic Sign, Five Sided, 48 Inch	645.2930
645.2640	Traffic Sign, 36x48x48 Inch Pennant	645.2940

MDG:RHF:B

