


*S. J. Sun & Associates
Copies*

TO: SUPERSEDED BY EB 88-001 EFFECTIVE 1/4/88	ENGINEERING BULLETIN NEW YORK STATE DEPARTMENT OF TRANSPORTATION	
	SUBJECT: UPDATE OF ENGINEERING INSTRUCTIONS Subject Code 7.20-1	
Distribution:	<input checked="" type="checkbox"/> Main Office <input checked="" type="checkbox"/> Regions <input checked="" type="checkbox"/> Special	Code: <u>EB 86-29</u>
APPROVED:	 _____ J. M. YOURNO, DIRECTOR, DESIGN BUREAU	Date: <u>10/20/86</u> Supersedes: EB 81-38

This Engineering Bulletin Expires _____

The following Engineering Instructions are active as of 10/20/86.

1972

2, 11, 21, 24, 37, 68, 70, 76, 82, 105, 106

1973

7, 12, 18, 26, 35, 38, 57, 67, 69, 81

1974

2, 3, 7, 8, 10, 11, 16, 17, 21, 23, 33, 38, 39, 41, 44, 49, 50, 53, 63, 67, 71, 80, 85, 91, 93, 95, 108

1975

1, 2, 4, 5A, 8, 13, 23, 24, 29, 31, 36, 47, 48, 49, 59, 64, 65, 69, 70, 74, 76, 78, 81, 84, 85, 86, 87, 88, 89, 90

1976

3, 10, 12, 14, 17, 18, 23, 26, 27, 28, 29, 31, 38, 51, 55, 57, 61, 67, 68, 70, 72, 74

1977

7, 10, 13, 14, 18, 22, 23, 24, 31, 33, 38, 39, 44, 45, 51, 55, 56, 57, 58

1978

1, 13, 14, 15, 16, 17, 19, 20, 21, 22, 24, 25, 28, 29, 30, 34, 39, 41, 43, 44, 45, 46, 56, 58, 60, 61

1979

1, 3, 4, 6, 7, 10, 11, 13, 15, 17, 21, 22, 23, 27, 30, 31, 33, 37, 38, 41, 42, 44, 46, 47, 48, 53, 55

Manual	Code EB 86-29	Date 10/20/86	Page 2
Subject: UPDATE OF ENGINEERING INSTRUCTIONS			

1980

3, 6, 8, 11, 13, 17, 18, 21, 23, 24, 25, 27, 31, 32, 34, 35, 39, 40, 41, 42, 43

1981

4, 5, 6, 10, 11, 14, 17, 18, 20, 25, 29, 32, 33, 34, 37, 40, 41, 43, 45, 48, 49, 50,
51

1982

1, 2, 3, 4, 5, 7, 9, 11, 12, 14, 15, 19, 21, 22, 23, 26, 27, 29, 32, 39, 40, 43, 44, 45,
47, 48, 49, 50, 53, 54, 55, 56, 57, 58, 61, 63, 64, 65, 66, 67, 70, 71, 73

1983

1, 3, 4, 5, 6, 7, 9, 11, 12, 13, 14, 15, 17, 19, 21, 22, 23, 25, 26, 29, 30, 31, 33, 35,
37, 38, 39, 42, 44, 45, 46, 48, 49, 50, 51, 53, 54, 55, 56, 57, 58

1984

1, 2, 3, 4, 6, 7, 8, 9, 10, 11, 12, 13, 16, 17, 18, 19, 22, 23, 24, 26, 28, 29, 30,
31, 32, 34, 35, 38, 39, 40, 41, 42, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 55, 56, 57,
58, 59, 60, 61

1985

1, 2, 3, 4, 6, 7, 8, 9, 10, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27,
28, 29, 30, 31, 32, 33, 35, 36, 37, 38, 39, 40, 41, 42, 43, 45, 46, 47, 48, 49, 50, 51,
52, 53, 54, 56

1986

1, 2, 3, 4, 5*, 6, 7, 8, 9, 10, 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24,
25, 26, 27, 28, 29, 30, 31, 32, 33, *34, *35

*Pending

Manual	Code	EB 86-29	Date	10/20/86	Page	3
Subject: UPDATE OF ENGINEERING INSTRUCTIONS						

This listing will be updated and distributed periodically. If discrepancies appear in this or future listings, please provide the EIIIS coordinator, in the Design Bureau, Bldg. 5, Room 308 with the correct information.

To ensure uniformity in the Engineering Information Issuance System we are requesting originators to conform with the following guidelines:

1. When superseding an issuance (Instruction or Bulletin) its number should be indicated on the replacement issuance.
2. When updating an issuance, retained information must be incorporated in the new issuance. The number of the replaced issuance should be indicated as superseded on the new issuance.
3. When the Engineering Issuance System is used to transmit Department publications, manuals, etc., the proper form to use is the Engineering Bulletin. If either minor instruction or routine information concerning the proper use of the transmitted material is required, the Engineering Bulletin should still be used. Use an Engineering Instruction only when either detailed instruction or important information regarding the use of transmitted material is required.