


TO: SUPERSEDED BY EB 89-001 EFFECTIVE 1/4/89	ENGINEERING BULLETIN NEW YORK STATE DEPARTMENT OF TRANSPORTATION
Distribution: <u>30</u> Main Office <u>32</u> Regions <u>34</u> Special	SUBJECT: UPDATE OF ENGINEERING INSTRUCTIONS Subject Code 7.20-1
APPROVED:  <hr/> P. J. CLARK, ACTING DIRECTOR, DESIGN BUREAU	Code: <u>EB 88-1</u> Date: <u>1/4/88</u> Supersedes: EB 86-29

The following Engineering Instructions are active as of 1/4/88. The issuance originator determines if it's unnecessary or inappropriate to issue an Engineering Instruction to Consultants. Those not sent to Consultants are circled.

1972

2, 11, 21, 24, 37, 68, 70, 76, (82), 105, 106

1973

(7), 12, 18, 26, 35, 38, 57, 67, 69

1974

2, (3), 7, 8, 10, 11, 16, 17, 21, (23), 33, (38), 39, 41, 44, 49, (50), 53, 63, 67, 71, 80, 85, 91, 93, 95, 108

1975

1, (2), 4, 5A, 8, 13, 23, 24, 29, (31), 36, 47, (48), 49, 59, 64, 65, (69), 70, 74, 76, 78, 81, 84, 85, 86, 87, 88, 89, 90

1976

3, 12, 14, 17, (18), 23, 26, 27, 28, 29, 31, 38, 51, 55, 57, (61), 67, 68, 70, 72, 74

1977

7, 10, 13, 14, 18, 22, 23, 24, 31, 33, 38, 39, (44), 45, 51, 55, (56), 57, 58

1978

1, 13, (14), 15, 16, (17), 19, 20, 21, 22, 25, 28, 30, 34, 39, 41, 43, 44, 45, (46), 56, 58, 60, (61)

Manual	Code EB 88-1	Date 1/4/88	Page 2
Subject: UPDATE OF ENGINEERING INSTRUCTIONS			

1979

1, 3, 4, 6, 7, 10, 11, 13, 15, 17, 21, 22, 23, (27), 30, (31), (33), 37, 38, 41, 42, 44, 46, 47, 48, 53, 55

1980

3, 6, 8, 11, 13, 17, 18, 21, 23, 24, 25, 27, 31, 32, 34, 35, 39, 40, 41, 42, 43

1981

4, 5, 6, 10, 11, 14, 17, 18, 20, 25, 29, 32, 33, 34, 37, 40, 41, 43, 45, 47, 48, 49, 50

1982

1, 2, 3, 4, 5, 6, 7, 9, 11, 12, 14, 15, 19, 21, 22, 23, 26, 27, 29, 32, 39, 40, 42, 43, 44, 45, 47, 48, 49, 50, 53, 54, 55, 56, 57, 58, 61, 63, 64, 65, 66, 67, 70, 71, 73

1983

3, 5, 6, 7, 9, 11, 12, 13, 14, 15, 17, 19, 21, 22, 23, 25, 29, 30, 31, 35, 37, 38, 39, 42, 44, 45, 46, 48, 49, 50, 51, 53, 54, 55, 56, 57, 58

1984

1, 2, 3, 4, 6, 7, 9, 10, 11, 12, 13, 16, 17, 18, 19, 22, 23, 24, 26, 28, 29, 30, 31, 32, 34, 35, 37, 38, 39, 40, 41, 42, 45, 46, 47, 48, 49, 50, 51, 52, 53, 55, 56, 57, 58, 59, 60, 61

1985

1, 2, 3, 6, 7, 8, 9, 10, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 35, 36, 37, 38, 39, 40, 41, 42, 43, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56

1986

1, 2, 3, 4, 6, 7, 8, 9, 10, 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 38, 41

1987

1, 3, 4, 5, 6, 7, 8, (9), 10, 11, 12, (13), 14, 15, 16, 18, 19, 20, 21, 22, 24, 25, 26, (27), 28, 29, 30, 31, 32, (33), (*34), 35, 36, 37, 38, 39, 40, 41

*Pending

Subject: UPDATE OF ENGINEERING INSTRUCTIONS

This listing is updated and distributed periodically. If discrepancies appear in this or future listings, please provide the EIIS coordinator, in the Design Bureau, Bldg. 4, Room G-01 with the correct information.

To ensure uniformity in the Engineering Information Issuance System we are requesting originators to conform with the following guidelines:

1. When superseding an issuance (Instruction or Bulletin) its number should be indicated on the replacement issuance.
2. When updating an issuance, retained information must be incorporated in the new issuance. The number of the replaced issuance should be indicated as superseded on the new issuance.
3. When the Engineering Issuance System is used to transmit Department publications, manuals, etc., the proper form to use is the Engineering Bulletin. If either minor instruction or routine information concerning the proper use of the transmitted material is required, the Engineering Bulletin should still be used. Use an Engineering Instruction only when either detailed instruction or important information regarding the use of transmitted material is required.