



To:		<i>New York State Department of Transportation</i> <b>ENGINEERING BULLETIN</b>	<b>EB</b> <b>01-030</b>
<i>Expires one year after issue unless replaced sooner</i>			
<b>Title: Superseding Outdated Engineering Instructions</b>			
<b>Distribution:</b> <input checked="" type="checkbox"/> Manufacturers (18) <input checked="" type="checkbox"/> Surveyors (33) <input checked="" type="checkbox"/> Main Office (30) <input checked="" type="checkbox"/> Consultants (34) <input checked="" type="checkbox"/> Local Govt. (31) <input checked="" type="checkbox"/> Contractors (39) <input checked="" type="checkbox"/> Regions/Agencies (32) <input type="checkbox"/> _____ ( )	<b>Approved:</b>  K. C. Hahn, EIS Administration <u>05/30/01</u> Date		

**ADMINISTRATIVE INFORMATION:**

This Engineering Bulletin is effective immediately. Ten Engineering Instructions are superseded, one EI is modified, one EB is modified and no EBs are superseded. Future versions of the Engineering Instructions and Bulletins [EIB] program will reflect the changes as noted.

**PURPOSE:**

This EB supersedes ten obsolete EIs that are noted as current in our database. The listed EIs contain outdated material and are superseded by this EB. Also, one error in EI 01-006 and two errors in EB 01-010 are noted and corrected.

**INFORMATION and IMPLEMENTATION:**

**EI 74-038** *Utility Relocation for Transportation Projects - Municipal Agreements*  
Per Design Quality Assurance Bureau: The current information in this EI is in the Manual of Procedure for Reimbursement on Utility Agreements.  
**EI 74-038 will be shown as: Superseded by the EB 01-030.**

**EI 81-010** *Traffic Signal Equipment Furnished by NYSDOT on Construction Contracts*  
Per Construction Division: The relevant information in this EI is in the Highway Design Manual, Chapter 21.  
**EI 81-010 will be shown as: Superseded by EB01-030.**

**EI 86-004** *Sign Lateral Clearance and Height Requirements*  
Per Traffic Engineering and Highway Safety Division: The relevant information has been incorporated into Standard Sheet M645-55, the guidance issued by EI 96-019 and the NYMUTCD.  
**EI 86-004 will be shown as: Superseded by EB01-030.**

**EI 86-007** *Alternate Tether Wire Sign Mounting*  
Per DQAB: The relevant information in the shelf note has been incorporated into Standard Sheet M680-6, issued by EI 96-019.  
**EI 86-007 will be shown as: Superseded by EB01-030.**

**EI 86-014** *Time Base Coordination Unit*  
Per DQAB: This EI is obsolete, the traffic signal controllers purchased by NYSDOT are capable of doing time-based coordination.  
**EI 86-014 will be shown as: Superseded by EB01-030.**

## EB 01-030 Page 2 of 2

### EI 88-032 *Operating Policy and Procedure Manual*

Per Structures Division: The information transmitted by the EI has been superseded by the Program and Project Management System (PPMS).

**EI 88-032 will be shown as: Superseded by EB01-030.**

### EI 89-018 *Guide Railing and Median Barrier Installed on Curbed Roadways*

Per DQAB: The relevant information in this EI is in the Highway Design Manual.

**EI 89-018 will be shown as: Superseded by EB01-030.**

### EI 94-038 *Engineer's Office and Laboratory Building Item 637.0XXX (English) & 637.0XXXM (Metric)*

Per CD: This EI is superseded by the Standard Specifications of 1995 (Metric).

**EI 94-038 will be shown as: Superseded by EB01-030.**

### EI 98-022 *Standard Specification Section 110-02 Value Engineering*

Per CD: This EI is superseded by Addendum # 1 to the Standard Specifications of 1995, dated 4/8/99.

**EI 98-022 will be shown as: Superseded by EB01-030.**

### EI 98-025 *Standard Specifications 01/02/95 Section 107-05 G - Equipment Involving Radioactive Materials*

Per CD: This EI is superseded by Addendum # 1 to the Standard Specifications of 1995, dated 4/8/99.

**EI 98-025 will be shown as: Superseded by EB01-030.**

**EI 01-006:** contained one error. The current EIB program has the correct information as noted below.

Under Administrative Information it states that the EI is effective with the projects submitted for the letting of September 6, 2001. However the Implementation paragraph incorrectly notes July 5, 2001 as the effective date. Please change all copies of EI 01-006 to reflect the correct Implementation date, **September 6, 2001**.

**EB 01-010** contained two errors. The current EIB program has the correct information as noted below.

<sup>6</sup>  
**EI ~~85~~-035:** The incorrect title is listed for EI 85-035. Please change all copies of EB 01-010 to reflect the correct title. ***Bituminous Surface Treatment Single Course for Payment for Maintenance Contracts.***

**EI 98-013:** The final sentence of the paragraph incorrectly starts with the wrong EI number, EI 95-053. [The information in the previous record for EI 95-053 is correct]. Please change all copies of EB 01-010 to reflect the correct information.

**EI 98-013 will be shown as: Superseded by Addendum # 2 to the Standard Specifications of 1995.**

### CONTACT:

Questions regarding this Engineering Bulletin should be directed to Lois Groskopf in the Design Quality Assurance Bureau at [518] 457-5597 or lgroskopf@gw.dot.state.ny.us.