

To:		New York State Department of Transportation ENGINEERING BULLETIN	EB 06-028
Expires one year after issue unless replaced sooner			
Title: CORRECTION TO EB 06-026			
Distribution: ☒ Manufacturers (18) ☒ Local Govt. (31) ☒ Agencies (32) ☒ Surveyors (33) ☒ Consultants (34) ☒ Contractors (39) ☐ _____ ()		Approved:  Daniel D'Angelo, P.E., Director Design Quality Assurance Bureau <u>6/06/06</u> Date	

ADMINISTRATIVE INFORMATION:

- **Effective Date.** This Engineering Bulletin (EB) is effective upon signature.
- **Superseded Issuances.** This EB does not supersede any previous EBs or Engineering Instructions (EIs).

PURPOSE: To identify a typographical error and its correction in EB 06-026.

TECHNICAL INFORMATION: Engineering Bulletin (EB) 06-026, "Highway Design Manual Revision No. 48 – Replacement Pages for EB 06-004" incorrectly shows the number for Engineering Instruction (EI) 95-003, "Requirements for Maintenance and Protection of Traffic During Nighttime Construction," in the last sentence of TECHNICAL INFORMATION as EI 99-003. This error is hereby corrected to EI 95-003. This EB should be attached to EB 06-026 for future reference.

CONTACT: Questions regarding this revision should be addressed to H.G. Rogers of the Design Quality Assurance Bureau at (518) 457-5597 or via e-mail at hgrogers@dot.state.ny.us.