


file

TO: SUPERSEDED BY EB 97-006 EFFECTIVE 2/14/97	<h1>ENGINEERING INSTRUCTION</h1> <p>NEW YORK STATE DEPARTMENT OF TRANSPORTATION</p>
Distribution: <input checked="" type="checkbox"/> Main Office <input checked="" type="checkbox"/> Regions <input type="checkbox"/> Special	Code: <u> EI 82-2 </u>
APPROVED:  <u>M. Tegza, Director, Final Plan Review Bureau</u>	Date: <u> 1/11/82 </u> Supersedes:

Item 15570.25. Cleaning Controlled Oxidizing Structural Steel - is being disapproved, effective January 4, 1982.

This procedure was used to provide a uniformly weathered appearance to the fascia beams made of controlled oxidizing steel. In practice it did not do this well enough to justify its cost and in some cases was more harmful than successful. There is no replacement item.

