



<b>TO:</b> <b>SUPERSEDED BY EB 81-038</b> <b>EFFECTIVE 8/31/81</b>	 <b>ENGINEERING BULLETIN</b> NEW YORK STATE DEPARTMENT OF TRANSPORTATION
<b>SUBJECT:</b> UPDATE OF ENGINEERING INSTRUCTIONS  Subject Code 7.20-1	
<b>Distribution:</b> <input checked="" type="checkbox"/> Main Office <input checked="" type="checkbox"/> Regions <input checked="" type="checkbox"/> Special	<b>Code:</b> EB 80-29
<b>APPROVED:</b>  Asst. Commissioner for Engineering & Chief Engineer	<b>Date:</b> 9/23/80  <b>Supersedes:</b> EI 72-108, EI 74-034 & EI 74-090

This Engineering Bulletin Expires \_\_\_\_\_

All Engineering Instructions distributed since 1972 under the Department's Engineering Issuance System have been reviewed. The following Instructions are still in force as of the date of issuance of this Bulletin:

1972

5, 6, 7, 9, 11, 14, 15, 16, 21, 22, 24, 25, 29, 35, 36, 37, 38, 46, 54, 60, 61, 64, 66, 68, 69, 70, 71, 75, 76, 77, 82, 84, 93, 98, 101, 102, 105, 106, 108.

1973

3, 4, 5, 6, 7, 11, 12, 14, 15, 18, 22, 23, 25, 26, 30, 32, 35, 36, 38, 39, 43, 45, 53, 54, 55, 57, 59, 60, 63, 65, 67, 69, 74, 81, 82, 83, 86, 90, 92.

1974

1, 2, 3, 5, 7, 8, 10, 11, 12, 13, 14, 16, 17, 18, 21, 23, 24, 30, 31, 33, 34, 35, 38, 39, 41, 42, 44, 47, 49, 50, 52, 53, 55, 59, 60, 63, 64, 65, 66, 67, 69, 71, 72, 75, 77, 80, 81, 83, 85, 91, 93, 95, 97, 98, 102, 104, 106, 107, 108, 114.

1975

1, 2, 4, 5A, 8, 9, 11, 13, 15, 18, 20, 23, 24, 28, 29, 31, 32, 36, 38, 39, 40, 42, 43, 45, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 59, 60, 61, 64, 65, 68, 69, 70, 72, 74, 75, 76, 77, 78, 79, 80, 81, 82, 84, 85, 86, 87, 88, 89, 90, 91, 94, 95.

1976

3, 4, 6, 10, 12, 14, 17, 18, 20, 21, 23, 25, 26, 27, 28, 29, 31, 35, 38, 41, 42, 43, 44, 47, 51, 54, 55, 56, 57, 61, 63, 65, 66, 67, 68, 69, 70, 72, 73, 74.

Manual	Code 7.20-1	Date 9/23/80	Page 2
Subject: UPDATE OF ENGINEERING INSTRUCTIONS			

1977

7, 10, 11, 12, 13, 14, 15, 16, 18, 19, 20, 22, 23, 24, 25, 27, 29, 31, 33, 34, 35, 36, 38, 39, 41, 44, 45, 47, 48, 49, 50, 51, 53, 55, 56, 57, 58.

1978

1, 2, 6, 8, 9, 10, 11, 12, 13, 14, 15, 16, 17, 19, 20, 21, 22, 23, 24, 25, 26, 28, 29, 30, 31, 34, 36, 37, 39, 41, 42, 43, 44, 45, 46, 47, 49, 51, 54, 56, 57, 58, 59, 60, 61.

1979

1, 2, 3, 4, 5, 6, 7, 8, 10, 11, 13, 15, 17, 18, 19, 20, 21, 22, 23, 24, 26, 27, 28, 30, 31, 33, 34, 36, 37, 38, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 55, 56.

1980

1, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12, 13, 14, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36.

This list will be updated periodically in order to eliminate obsolete Instructions from the System. The next update will be after the Construction Division issues their Construction Supervision Manual.

In order to keep the number of Instructions in force at any one time to a minimum, we have the following recommendations:

1. When a new Instruction supersedes an existing Instruction, the issuer should continue to note the superseded Instruction so that it can be removed from the active list.
2. If a new Instruction updates an existing Instruction, those portions of the existing Instruction that remain in effect should be incorporated into the new issuance by the writer whenever possible. The old Instruction can then be superseded.
3. When the Engineering Issuance System is used to transmit Department publications, manuals, etc., the proper form to use is the Engineering Bulletin. If minor instructions or routine information concerning the proper use of the transmitted material are required, the Engineering Bulletin should still be used. Use an Engineering Instruction only when detailed instructions or important information regarding the use of transmitted material are required.