


TO: SUPERSEDED BY EB 86-029 EFFECTIVE 10/20/86	ENGINEERING BULLETIN NEW YORK STATE DEPARTMENT OF TRANSPORTATION	
	SUBJECT: UPDATE OF ENGINEERING INSTRUCTIONS Subject Code 7.20-1	
Distribution:	<input checked="" type="checkbox"/> Main Office <input type="checkbox"/> Regions <input type="checkbox"/> Special	Code: <u>EB 81-38</u> Date: <u>8/31/81</u> Supersedes: EI 72-009, EI 74-014, EI 76-025, EI 76-073 & EB 80-029
APPROVED:  Asst. Commissioner for Engineering and Chief Engineer		

This Engineering Bulletin Expires _____

The following Engineering Instructions are active as of 8/31/81.

1972

2, 7, 11, 21, 24, 37, 68, 70, 76, 82, 105, 106

1973

7, 12, 18, 26, 35, 38, 57, 67, 69, 74, 81, 90

1974

2, 3, 7, 8, 10, 11, 16, 17, 21, 23, 33, 38, 39, 41, 44, 49, 50, 53, 63, 67, 71, 80, 85, 91, 93, 95, 108

1975

1, 2, 4, 5A, 8, 13, 15, 23, 24, 29, 31, 36, 47, 48, 49, 56, 59, 64, 65, 69, 70, 74, 76, 77, 78, 81, 84, 85, 86, 87, 88, 89, 90

1976

3, 10, 12, 14, 17, 18, 23, 26, 27, 28, 29, 31, 35, 38, 43, 51, 54, 55, 56, 57, 61, 65, 67, 68, 69, 70, 72, 74

1977

7, 10, 13, 14, 18, 22, 23, 24, 25, 26, 29, 31, 33, 38, 39, 44, 45, 47, 50, 51, 53, 55, 56, 57, 58

Subject: UPDATE OF ENGINEERING INSTRUCTIONS

1978

1, 2, 9, 12, 13, 14, 15, 16, 17, 19, 20, 21, 22, 24, 25, 28, 29, 30, 34, 39, 41, 43, 44, 45, 46, 54, 56, 57, 58, 60, 61

1979

1, 2, 3, 4, 6, 7, 8, 10, 11, 13, 15, 17, 18, 19, 21, 22, 23, 24, 27, 28, 30, 31, 33, 34, 36, 37, 38, 41, 42, 44, 45, 46, 47, 48, 50, 52, 53, 55, 56

1980

1, 3, 5, 6, 7, 8, 9, 11, 12, 13, 16, 17, 18, 20, 21, 22, 23, 24, 25, 27, 28, 29, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45

1981

1, 3, 4, 5, 6, 7, 10, 11, 12, 13, 14, 15, 16, 17, 18, 20, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35

Please note that EI's 72-2 and 77-26, which were inadvertently omitted in EB 80-29 are still active.