

TO:	ENGINEERING BULLETIN		
	NEW YORK STATE DEPARTMENT OF TRANSPORTATION		
SUBJECT: UPDATE OF ENGINEERING INSTRUCTIONS			
Subject Code 7.20-1			
Distribution:	<input checked="" type="checkbox"/> Main Office	<input checked="" type="checkbox"/> Regions	<input checked="" type="checkbox"/> Special
			Code: <u>EB 90-1</u>
			Date: <u>1/1/90</u>
APPROVED:	<i>J M Yourno</i>		Supersedes:
J. M. Yourno, Director, Consultant Mgmt. Bur.			EB 89-1

This Engineering Bulletin Expires _____

The following Engineering Instructions are active as of 1/2/90. - The issuance originator determines if it's appropriate to issue an Engineering Instruction to Consultants. Those not sent to Consultants are circled.

1972

② 11, 21, 24, 37, 68, 70, 76, ⑧ 105, 106

1973

⑦ 12, 18, 26, 35, 38, 57, 67, 69

1974

2, ③ 7, 8, 10, 11, 16, 17, 21, ② 23, 33, ③ 38, 39, 41, 44, 49, ⑤ 50, 53, 63, 67, 71, 80, 85, 93, 95, 108

1975

1, ② 4, 5A, 8, 13, 23, 24, 29, 36, 47, ④ 48, 49, 59, 64, 65, ⑥ 69, 70, 74, 76, 78, 81, 84, 85, 86, 87, 88, 89, 90

1976

3, 12, 14, 17, ⑩ 18, 23, 26, 27, 28, 29, 31, 38, 51, 55, 57, ⑪ 61, 67, 68, 70, 72, 74

1977

7, 10, 13, 14, 18, 22, 23, 24, 31, 33, 38, 39, ⑫ 44, 45, 51, 55, ⑬ 56, 57, 58

1978

1, 13, ⑭ 14, 15, 16, ⑮ 17, 19, 21, 22, 25, 28, 30, 34, 39, 41, 43, 44, 45, ⑯ 46, 56, 58, 60, ⑰ 61

Subject: UPDATE OF ENGINEERING INSTRUCTIONS

1979

1, 3, 4, 6, 7, 10, 11, 13, 15, 17, 21, 22, 23, (27), 30, (31), (33), 37, 38, 41, 42, 44,
46, 47, 48, 53, 55

1980

3, 6, 8, 11, 13, 17, 18, 21, 23, 24, 25, 27, 31, 32, 34, 35, 39, 40, 41, 42, 43

1981

4, 5, 6, 10, 11, 14, 17, 18, 25, 29, 33, 34, 37, 40, 41, 43, 45, 47, 48, 49, 50

1982

1, 2, 3, 4, 5, 6, 7, 9, 11, 12, 14, 15, 19, 21, 22, 23, 26, 27, 29, 32, 39, 40, 42,
43, 44, 45, 47, 48, 49, 50, 53, 54, 55, 56, 57, 58, 61, 63, 64, 65, 66, 67, 70, 71, 73

1983

3, 5, 6, 7, 9, 11, 12, 13, 14, 15, 17, 19, 21, 22, 23, 25, 29, 30, 31, 35, 37, 38,
39, 42, 44, 45, 46, 48, 49, 50, 51, 53, 54, 56, 58

1984

1, 2, 3, 4, 7, 9, 10, 11, 12, 13, 17, 18, 19, 22, 23, 24, 26, 28, 29, 30, 31, 32,
34, 35, 37, 38, 39, 40, 41, 45, 46, 47, 48, 49, 50, 51, 52, 53, 55, 56, 57, 58, 59,
60, 61

1985

1, 2, 3, 6, 7, 8, 9, 10, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 24, 25, 26, 27,
28, 29, 30, 31, 32, 35, 36, 37, 38, 40, 41, 42, 43, 45, 46, 47, 48, 49, 50, 51, 52,
53, 54, 55, 56

1986

1, 3, 4, 6, 7, 8, 9, 11, 12, 13, 14, 15, 16, 17, 20, 21, 22, 23, 24, 25, 26, 27, 28,
29, 30, 31, 32, 33, 34, 35, 36, 41

1987

3, 4, 5, 6, 7, 8, 12, (13), 14, 15, 16, 18, 20, 21, 22, 24, 25, 26, (27), 28, 29, 30,
31, (33), 35, 36, 37, 38, 39, 40, 41

1988

1, 2, (3), 4, 5, (6), 7, 8, 9, 10, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 23, 24, 25,
26, 27, 29, 30, 31, (32), 34, 35, 36, 37, 38, 39, 40, 41, (42), 43

1989

1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12, 13, 14, 15, (16), 17, 18, 19, 20, 21, 22, 23,
24, 25, (26), 26, (27), 28, 29, 30, (31), 32, 33

Subject: UPDATE OF ENGINEERING INSTRUCTIONS

This listing is updated and distributed periodically. If discrepancies appear in this or future listings, please provide the EIIS coordinator, in the Design Bureau, Bldg. 4, Room G-01 with the correct information.

To ensure uniformity in the Engineering Information Issuance System (EIIS) we are requesting originators to conform with the following guidelines:

1. When superseding an issuance (Instruction or Bulletin) its number should be indicated on the replacement issuance.
2. When updating an issuance, retained information must be incorporated in the new issuance. The number of the replaced issuance should be indicated as superseded on the new issuance.
3. When the Engineering Information Issuance System is used to transmit Department publications, manuals, etc., the proper form to use is the Engineering Bulletin. If either minor instruction or routine information concerning the proper use of the transmitted material is required, the Engineering Bulletin should still be used. Use an Engineering Instruction only when either detailed instruction or important information regarding the use of transmitted material is required.