



To:		New York State Department of Transportation <b>ENGINEERING          BULLETIN</b>	<b>EB</b> <b>98-060</b>
Expires one year after issue unless replaced sooner			
Title: <b>Superseding Outdated Engineering Instructions</b>			
Distribution: <input checked="" type="checkbox"/> Manufacturers (18) <input checked="" type="checkbox"/> Surveyors (33) <input checked="" type="checkbox"/> Main Office (30) <input checked="" type="checkbox"/> Consultants (34) <input checked="" type="checkbox"/> Local Govt. (31) <input checked="" type="checkbox"/> Contractors (39) <input checked="" type="checkbox"/> Regions/Agencies (32) <input type="checkbox"/> _____ ( )		Approved:  _____ Kenneth C. Hahn, EIS Administrator      11/17/98 <span style="float: right;">Date</span>	

The continuing review of Engineering Instructions by the Design Quality Assurance Bureau has identified 24 obsolete EIs that are listed in our database as current. These EIs contain outdated material or have been superseded by newer issuances. Future versions of the EIB Program, starting in 1999, will reflect the following changes:

**EI 72-009** "Obtaining Plant Materials From the Department of Environmental Conservation"  
 Per Landscape Architecture Bureau: This EI is obsolete. EI 72-009 was included in EB 80-029, *Update of Engineering Instructions*, the complete list of active EIs as of 9/23/80. It was not included in EB 81-038, *Update of Engineering Instructions*, the complete list of active EIs as of 8/31/81.  
**EI 72-009 will be shown as: Superseded by EB 81-038.**

**EI 72-076** "Bituminous Paving-Construction Procedures"  
 Per Materials Bureau: This EI is obsolete; the construction procedure it contains is no longer used.  
**EI 72-076 will be shown as: Superseded by EB 98-060.**

**EI 75-005A** "Design Criteria for Bridges: 75-1 Stepped Footings"  
 Per Structures Division: EB 98-014, *Bridge Manual*, announced the availability of the Bridge Manual and superseded a list of EIs that were no longer needed or were incorporated into the manual. EI 75-005A (75-999) was mistakenly omitted from the list of superseded EIs included in EB 98-014.  
**EI 75-005A (75-999) will be shown as: Superseded by EB 98-060.**

**EI 75-029** "Skid Resistance Testing"  
 Per Materials Bureau: This EI is obsolete; the described schedules are not followed and the attached Pavement Skid Test Request Form is no longer used.  
**EI 75-029 will be shown as: Superseded by EB 98-060.**

## EB 98-060 Page 2 of 4

**EI 78-030**     *"Soil Test Method STM-3 Test Method for Magnesium Sulfate Soundness of Granular Materials"*

Per Geotechnical Engineering Bureau: Soil Test Method STM-11, announced by EI 82-066, *"Effective Date for STM-11 . . . ,"* replaced Soil Test Method STM-3. However, EI 82-066 omitted a statement superseding EI 78-030.

**EI 78-030 will be shown as: Superseded by EB 98-060.**

**EI 80-024**     *"Asphalt Price Adjustment"*

Per Construction Division: This EI is obsolete; the relevant information about this subject was included in the Standard Specifications of January 2, 1990 and is in all contract proposals when and where necessary.

**EI 80-024 will be shown as: Superseded by the NYSDOT Standard Specifications of January 2, 1990.**

**EI 80-043**     *"Fuel Price Adjustment - Contract Payments"*

Per CD: This EI is obsolete; the relevant information about this subject was included in the Standard Specifications of January 2, 1990 and in all contract proposals when and where necessary.

**EI 80-043 will be shown as: Superseded by the NYSDOT Standard Specifications of January 2, 1990.**

**EI 81-011**     *"Asphalt Price Adjustment - 1981"*

Per CD: This EI is obsolete; the relevant information about this subject was included in the Standard Specifications of January 2, 1990 and in all contract proposals when and where necessary.

**EI 81-011 will be shown as: Superseded by the NYSDOT Standard Specifications of January 2, 1990.**

**EI 81-037**     *"Revisions to Plant Item Numbers in The Standard Pay Items Catalog"*

Per LAB: This EI is obsolete; it described changes made to the Standard Contract Pay Items Catalog. The 1990 catalog contained the changes.

**EI 81-037 will be shown as: Superseded by Standard Contract Pay Items, January 2, 1990.**

**EI 81-047**     *"Continuous Structure Deck Slab Placements"*

Per SD: EB 98-014, *Bridge Manual*, announced the availability of the Bridge Manual and superseded a list of EIs that were no longer needed or were incorporated into the manual. EI 81-047 was mistakenly omitted from the list of superseded EIs.

**EI 81-047 will be shown as: Superseded by EB 98-060.**

**EI 81-048**     *"Transverse Joint Supports for Portland Cement Concrete Pavements"*

Per Design Quality Assurance Bureau: This EI disapproved two special specifications. These items are shown as disapproved in the EEHS Special Specifications Catalog.

**EI 81-048 will be shown as: Superseded by EB 98-060.**

**EI 82-003** *"Membrane Waterproofing System"*

Per DQAB: This EI is obsolete; it described a revision done to a special specification. The current revised special specification is a Main Office insert.

**EI 82-003 will be shown as: Superseded EB by 98-060.**

**EI 82-064** *"Fuel and Asphalt Price Adjustment"*

Per CD: This EI is obsolete; the relevant information about this subject was included in the Standard Specifications of January 2, 1990 and in all contract proposals when and where necessary.

**EI 82-064 will be shown as: Superseded by the NYSDOT Standard Specifications of January 2, 1990.**

**EI 86-021** *"Sidewalk Curb Ramp Details"*

Per LAB: This EI was modified by Chapter 18 of the Highway Design Manual and the repeal of Section 330 of the Highway Law. It was superseded by the issuance of EI 98-029, *Sidewalk Curb Ramp Details*. However, EI 98-029 omitted a statement superseding EI 86-021.

**EI 86-021 will be shown as: Superseded by EB 98-060.**

**EI 90-025** *"Tubular Markers"*

Per DQAB: This EI is obsolete; it disapproved one item and confirmed the approval of another item that was in the Standard Specifications of January 2, 1990

**EI 90-025 will be shown as: Superseded by EB 98-060.**

**EI 93-039** *"Highway Design Manual, Chapter 17 Landscape Development"*

Per DQAB: This EI is obsolete; it announced that Chapter 17 of the Highway Design Manual was rescinded. The Table of Contents for the HDM states that Chapter 17 has been rescinded.

**EI 93-039 will be shown as: Superseded by EB 98-060.**

**EI 94-023** *"Highway Design Manual Revision No. 21, Chapter 2 Design Criteria"*

Per DQAB: This is an Engineering Bulletin type issuance that announces the availability of the noted chapter. The Table of Contents for the HDM provides the latest revision date for this chapter.

**EI 94-023 will be shown as: Superseded by EB 98-060.**

**EI 95-013** *"Highway Design Manual Revision No. 22, Chapter 10 Roadside Design, Guide Rail and Appurtenances"*

Per DQAB: This is an Engineering Bulletin type issuance that announces the availability of the noted chapter. The Table of Contents for the HDM provides the latest revision date for this chapter.

**EI 95-013 will be shown as: Superseded by EB 98-060.**

**EI 95-022** *"Highway Design Manual Revision No. 23, Chapter 3 Typical Sections, Chapter 9 Soils and Foundations and Chapter 10 Roadside Design"*

Per DQAB: This is an Engineering Bulletin type issuance that announces the availability of the noted chapter. The Table of Contents for the HDM provides the latest revision date for this chapter.

**EI 95-022 will be shown as: Superseded by EB 98-060.**

## EB 98-060 Page 4 of 4

### EI 95-037 *"Highway Design Manual Revision No. 24, Chapter 12 Highway Lighting"*

Per DQAB: This is an Engineering Bulletin type issuance that announces the availability of the noted chapter. The Table of Contents for the HDM provides the latest revision date for this chapter.

**EI 95-037 will be shown as: Superseded by EB 98-060.**

### EI 95-052 *"Highway Design Manual Revision No. 25, Chapter 5 Basic Design"*

Per DQAB: This is an Engineering Bulletin type issuance that announces the availability of the noted chapter. The Table of Contents for the HDM provides the latest revision date for this chapter.

**EI 95-052 will be shown as: Superseded by EB 98-060.**

### EI 96-039 *"Distribution of Bridge Design Data Sheets . . ."*

Per SD: EB 97-044 *Index: Bridge Design Data Sheets; Guideline Drawings; Bridge Detail Sheets* contained the current index of the three noted Structures Division Issuances. However, EI 96-039 was omitted from the list of rescinded EIs.

**EI 96-039 will be shown as: Superseded by EB 98-060.**

### EI 97-001 *"Bridge Detail (BD) Sheets . . . Steel Details"*

Per SD: EB 97-044 *Index: Bridge Design Data Sheets; Guideline Drawings; Bridge Detail Sheets* contained the current index of the BD sheets. However, EI 97-001 was omitted from the list of rescinded EIs.

**EI 97-001 will be shown as: Superseded by EB 98-060.**

### EI 97-006 *"Bridge Detail (BD) Sheets . . . Prestressed Concrete Details"*

Per SD: EB 97-044 *Index: Bridge Design Data Sheets; Guideline Drawings; Bridge Detail Sheets* contained the current index of the BD sheets. However, EI 97-006 was omitted from the list of rescinded EIs.

**EI 97-006 will be shown as: Superseded by EB 98-060.**

Questions regarding this Engineering Bulletin should be directed to Lois Groskopf in the Design Quality Assurance Bureau at [518] 457-5597.