



To:		New York State Department of Transportation ENGINEERING BULLETIN	EB 99-072
<i>Expires one year after issue unless replaced sooner</i>			
Title: SUBBASE COURSE PAY ITEMS			
Distribution: <input checked="" type="checkbox"/> Manufacturers (18) <input checked="" type="checkbox"/> Surveyors (33) <input checked="" type="checkbox"/> Main Office (30) <input checked="" type="checkbox"/> Consultants (34) <input checked="" type="checkbox"/> Local Govt. (31) <input checked="" type="checkbox"/> Contractors (39) <input checked="" type="checkbox"/> Regions/Agencies (32) <input type="checkbox"/> _____ ()		Approved: <div style="text-align: center;">  <hr/> P. J. Bellair, Director, Design/Quality Assurance Bureau </div> <div style="text-align: right;"> <u>9-29-99</u> Date </div>	

Administrative Information. This Engineering Bulletin modifies EB 99-066. It will be effective on all contracts that use Addendum #2. It announces a modification to ADDENDUM NO. 2 TO THE STANDARD SPECIFICATIONS OF 1995.

Background. Section 304 of the Standard Specifications was completely rewritten for Addendum #2. Included in the rewrite was reusing item numbers for different items. This confounding of item numbers was not noticed until recently.

Transmitted Materials. This E.B. distributes the shelf note, "SUBBASE COURSE PAY ITEMS " which assigns new pay numbers for use with Addendum #2. This shelf note will be added by Design Quality Assurance Bureau to all Proposals let on or after January 13, 2000 to contracts using standard §304 items.

Action by Designers. For Contracts let before January 13 but after November 1, designers will have to determine if their project uses any subbase course items, and Addendum #2. If a project in these lettings includes subbase course, and uses Addendum #2 (as opposed to being slipped from an earlier letting), the designer must request an amendment to include the attached shelf note to correct the item numbers. Item numbers 304.02 M through 304.06 M have been disapproved, but can be used for those projects which do not refer to Addendum #2.

Contact Person. Any questions pertaining to the item numbers in this EB may be addressed to Richard Marriott of the Design Quality Assurance Bureau, at (518) 457-6393. Questions about the changes to the subbase specification should be addressed to Don Dwyer at (518) 457-4724.

SUBBASE COURSE PAY ITEMS

Make the following changes to Addendum #2 to the Standard Specifications of January 2, 1995:

Page III-4

Replace lines 43 through 47 with the following:

"304.11 M	Subbase Course, Type 1	Cubic Meter
304.12 M	Subbase Course, Type 2	Cubic Meter
304.13 M	Subbase Course, Type 3	Cubic Meter
304.14 M	Subbase Course, Type 4	Cubic Meter
304.15 M	Subbase Course, Optional Type	Cubic Meter"