



To: <b>SUPERSEDED BY EB 01-006</b> <b>EFFECTIVE 1/8/01</b>		<i>New York State</i> <i>Department of</i> <i>Transportation</i> <b>ENGINEERING</b> <b>BULLETIN</b>	<b>EB</b> <b>00-075</b>
<i>Expires one year after issue unless replaced sooner</i>			
Title: <b>TRANSITION BETWEEN HPBO CORRUGATED BEAM GUIDE RAILING AND CONCRETE BARRIER</b>			
Distribution: <input checked="" type="checkbox"/> Manufacturers (18) <input checked="" type="checkbox"/> Surveyors (33) <input checked="" type="checkbox"/> Main Office (30) <input checked="" type="checkbox"/> Consultants (34) <input checked="" type="checkbox"/> Local Govt. (31) <input checked="" type="checkbox"/> Contractors (39) <input checked="" type="checkbox"/> Regions/Agencies (32) <input type="checkbox"/> _____ ( )		Approved:  <hr/> Philip Clark, Deputy Chief Engineer, Design Division <span style="float: right;">           11/15/00            Date         </span>	

**ADMINISTRATIVE INFORMATION.** This Engineering Bulletin is effective with projects submitted for the letting of 05/03/01. If designers decide to incorporate these details with a project having an earlier letting date, they must provide the Standard Sheets established in this Engineering Bulletin and the shelf note established in EI 00-040. No Engineering Bulletins are superseded hereby.

**PURPOSE.** The purpose of this bulletin is to issue the Standard Sheets listed below.

**TRANSMITTED MATERIALS.** This bulletin transmits the following Standard Sheets:

- ◆ M606-38 Transition Between Heavy Post Blocked-Out Corrugated Beam Guide Railing and Concrete Barrier (Sheet 1 of 2)
- ◆ M606-39 Transition Between Heavy Post Blocked-Out Corrugated Beam Guide Railing and Concrete Barrier (Sheet 2 of 2)
- ◆ M606-40 Transition Between Heavy Post Blocked-Out Corrugated Beam Guide Railing and Single Slope Half Section Concrete Barrier
- ◆ M606-41 Transition Between Heavy Post Blocked-Out Corrugated Beam Guide Railing and Half Section Concrete Jersey Barrier

**IMPLEMENTATION.** The attached Standard Sheets showing the aforementioned transitions are to be used in association with items 606.8707 M and 606.8757 M. These new pay items will be established through the use of a shelf note (See EI 00-040.)

**CONTACT PERSON.** Arvind Salgam or Pratip Lahiri of the Design Quality Assurance Bureau at (518) 457-5855 and (518) 457-4090, respectively.