


To: MODIFIED BY EB 01-030 EFFECTIVE 5/30/01		New York State Department of Transportation ENGINEERING BULLETIN	EB 01-010
Title: SUPERSEDING OUTDATED ENGINEERING INSTRUCTIONS			
Distribution: ☒ Manufacturers (18) ☒ Surveyors (33) ☒ Main Office (30) ☒ Consultants (34) ☒ Local Govt. (31) ☒ Contractors (39) ☒ Regions/Agencies (32) ☐ _____ ()	Approved:  Kenneth C. Hahn, EIS Administration <u>02/06/01</u> Date		

ADMINISTRATIVE INFORMATION:

This Engineering Bulletin is effective immediately. No EBs are superseded. Future versions of the Engineering Instructions and Bulletins [EIB] program will reflect the changes noted.

PURPOSE:

This EB supersedes 28 obsolete Engineering Instructions that are noted as current in our database. The listed EIs contain outdated material and are superseded by the issuances noted in the individual record.

INFORMATION and IMPLEMENTATION:

EI 74-067 *Utility Involvement on Reconditioning and Preservation Projects*

Per Design Quality Assurance Bureau: This EI was supplemented [partially superseded] by Part 131 Accommodation of Utilities Within State Highway Right of Way. It was superseded by Chapter 10 of the Highway Design Manual. However EI 95-013, which announced the HDM, omitted this EI from the list of superseded EIs.

EI 74-067 will be shown as: Superseded by the EB 01-010.

EI 80-006 *Inclusion of Sign Area on the Plans*

Per DQAB: This EI is obsolete. The information included in it was incorporated into the Standard Specifications of January 2, 1985.

EI 80-006 will be shown as: Superseded by EB 01-010.

EI 80-013 *Building Requirements & Use Agreements for the Installation of Temporary Information Centers in Rest Areas*

Per Landscape Architecture Bureau: This EI is no longer pertinent due to the formulation of newer rest area policies.

EI 80-013 will be shown as: Superseded by EB 01-010.

EI 80-031 *Relocation of Utility Poles on R&P Projects*

Per DQAB: This EI was supplemented [partially superseded] by Part 131 Accommodation of Utilities Within State Highway Right of Way. It was superseded by Chapter 10 of the HDM. However EI 95-013, which announced the HDM chapter, omitted this EI from the list of superseded EIs.

EI 80-031 will be shown as: Superseded by the EB 01-010.

EI 81-025 *Procedure for Inventorying and Inspecting New and Reconstructed Bridges*

Per Structures Division: This EI was made obsolete by the decentralization of the Department; the regions have developed procedures which are in use.

EI 81-025 will be shown as: Superseded by EB 01-010.

EB 01-010 Page 2 of 3

EI 81-050 *Changes in Specifications (Plastic Filler Fabric)*

Per Geotechnical Engineering Bureau: This EI refers to items that have been updated; they are now included in Addendum #2 to the Standard Specifications of 1995, Dated November 4, 1999.

EI 81-050 will be shown as: Superseded by EB 01-010.

EI 82-021 *Municipal Utility Relocation on Federal Aid Off-System Highway Projects*

Per DQAB: This EI was superseded by the Locally Administered Federal Aid Procedures Manual, Chapter 10, Utilities and Railroads, [draft of 09/03/99]. There was no issuance announcing the manual.

EI 82-021 will be shown as: Superseded by EB 01-010.

EI 82-048 *Motorist Services Signs & Tourist Oriented Business Directional Signs*

Per DQAB: This EI is obsolete. The special specification was disapproved.

EI 82-048 will be shown as: Superseded by EB 01-010.

EI 82-065 *Pressure Relief Joints*

Per DQAB: This EI was superseded by EI 92-026, however it was omitted from the list of superseded EIs.

EI 82-065 will be shown as: Superseded by EB 01-010.

EI 82-066 *Soil Test Method STM-11 "Test Method for Magnesium Sulfate Soundness of Granular Materials"*

Per GEB: This EI was superseded by Soil Test Method STM-21 "Test Method for Magnesium Sulfate Soundness of Granular Materials". This method was announced by EB 94-025. However, the EB omitted stating that this EI was superseded.

EI 82-066 will be shown as: Superseded by EB 01-010.

EI 83-031 *Standard Sheet 645-8R1 Standard Regulatory and Warning Signs*

Per DQAB: This EI is obsolete. The information included in it was incorporated into the Standard Specifications of 1995 (Metric). However EB 95-023, which announced its publication, did not include a list of superseded EI's.

EI 83-031 will be shown as: Superseded by NYSDOT Standard Specifications of 1995 (Metric).

EI 83-039 *Traffic Signal Pole Design*

Per DQAB: This EI is obsolete. The information included in it was incorporated into the Standard Specifications of January 2, 1985.

EI 83-039 will be shown as: Superseded by EB 01-010.

EI 83-046 *Separate Pay Items for Automatic Sprinkler Systems for Fire Control*

Per DQAB: The guidance contained in this EI is obsolete.

EI 83-046 will be shown as: Superseded by EB 01-010.

EI 83-050- *Review of Consultant's Requests for Payment*

Per Consultant Management Bureau: This EI was superseded by the Design Consultant Manual, dated October 1995. There was no issuance announcing the manual.

EI 83-050 will be shown as: Superseded by EB 01-010.

EI 84-041 *Material Details for Transverse Joint Systems*

Per Materials Bureau: These instructions were included in the Standard Specifications of 1995 (Metric) under item 705-15. However EB 95-023, which announced its publication, did not include a list of superseded EI's.

EI 84-041 will be shown as: Superseded by the NYSDOT Standard Specifications of 1995 (Metric).

EI 84-050 *Maintaining Schedules for Critical Activities in the Design Process*

Per DQAB: This information was superseded by the Design Procedures Manual; however EB 94-036, which announced the availability of the manual, omitted a list of superseded EIs.

EI 84-050 will be shown as: Superseded by EB 01-010.

EI 85-006 *Bridge Design Manual; Design Criteria for Bridges; Modifications to EI 79-041.*

Per SD: This information is included in the Bridge Manual, second edition, issued by EB 99-039, and Addendum #1, issued by EB 00-024. This EI was omitted from the lists of superseded EIs included in either of the EBs.

EI 85-006 will be shown as: Superseded by EB 01-010.

EI 85-017 *BDM; Standard Specifications for Highway Bridges; Wind Forces Applied to Noise Barriers*

Per SD: This information is included in the AASHTO Noise Barrier Specifications.

EI 85-017 will be shown as: Superseded by EB 01-010.

EI 85-029 *Concrete Mix Design Program L530011*

Per MB: This program was replaced by a Quattro-Pro Mix Design Program, effective January 2000. This change was announced at a Regional Materials Engineers meeting.

EI 85-029 will be shown as: Superseded by EB 01-010.

EI 85-046 *Rate of Pure Live Seed per Acre*

Per LAB: This EI is obsolete; the current information on this subject is addressed through staff training.

EI 85-046 will be shown as: Superseded by EB 01-010.

EI 85-053 *Bridge Design Manual; Standard Details for Highway Bridges, Special Specifications for Bridges*

Per SD: This EI issued English specifications that are now obsolete.

EI 85-053 will be shown as: Superseded by EB 01-010.

EI 86-035 *Section 490 - Cold Milling*

Per DQAB: The specification was disapproved 10/04/90. The policy was in EI 92-026, which superseded EI 86-035. However, EI 92-026 did not include EI 86-035 in the section of superseded issuances.

EI 86-035 will be shown as: Superseded by EB 01-010.

EI 89-008 *Section 490 - Cold Milling*

Per DQAB: The specification was included in the Standard Specifications of 1990. The policy was in EI 92-026, which superseded EI 89-008. However, EI 92-026 did not include EI 89-008 in the section of superseded issuances.

EI 89-008 will be shown as: Superseded by EB 01-010.

EI 90-039 *Structural Concrete Distress/Treatment Guidelines*

Per SD: This EI refers to English specifications that are now obsolete.

EI 90-039 will be shown as: Superseded by EB 01-010.

EI 92-020 *Demolition Specification*

Per DQAB: The guidance in this EI is now included in the Bridge Manual and § 202 is in the Standard Specifications of 1995 (Metric).

EI 92-020 will be shown as: Superseded by EB 01-010.

EI 95-040 *Specifications for Bridge Construction Items 17551.0302 and Item 17551.0395*

Per SD: This EI issued English specifications that are now obsolete.

EI 95-040 will be shown as: Superseded by EB 01-010.

EI 95-053 *Design Guidelines for the use of Penetrating and Coating Type Sealers for Concrete*

Per SD: This information is included in the Bridge Manual, second edition, issued by EB 99-039, and Addendum#1, issued by EB 00-024. This EI was omitted from the lists of superseded EIs included in the EBs.

EI 95-053 will be shown as: Superseded by EB 01-010.

EI 98-013 *Transmittal of Revised Specifications for concrete Overlays and Specialized Concrete Overlay of Structural Slabs*

Per MB: This information is included in Addendum #2 to the Standard Specifications of 1995. However EB 99-066, which announced the availability of the addendum, omitted a list of superseded EIs.

EI 95-053 will be shown as: Superseded by Addendum #2 to the Standard Specifications of 1995.

CONTACT:

Questions regarding this Engineering Bulletin should be directed to Lois Groskopf in the Design Quality Assurance Bureau at [518] 457-5597 or lgroskopf@gw.dot.state.ny.us.