



To:		New York State Department of Transportation ENGINEERING BULLETIN	EB 05-001
		Expires one year after issue unless replaced sooner	
Title: SUPERSEDING OUTDATED ENGINEERING INSTRUCTIONS			
Distribution: <input checked="" type="checkbox"/> Manufacturers (18) <input checked="" type="checkbox"/> Surveyors (33) <input checked="" type="checkbox"/> Local Govt. (31) <input checked="" type="checkbox"/> Consultants (34) <input checked="" type="checkbox"/> Agencies (32) <input checked="" type="checkbox"/> Contractors (39) <input type="checkbox"/> _____ ()		Approved:  _____ Hal G. Rogers, P.E., EIS Administrator	
		01/03/05 Date	

ADMINISTRATIVE INFORMATION:

- **Effective Date.** This Engineering Bulletin (EB) is effective immediately.
- **Superseded Issuances.** This EB supersedes EI 95-047, EI 98-037, and EI 01-025.

PURPOSE:

This EB supersedes three (3) obsolete Engineering Instructions (EIs) that are noted as current in the EIEB3 program database. The EIs listed below contain outdated material and are superseded by the issuances noted in the individual listing.

INFORMATION AND IMPLEMENTATION:

EI 95-047 *Construction Signs and Reflective Sheeting*

Per Design Quality Assurance Bureau: This EI was superseded by EB 99-066 *Addendum No. 2 to the Standard Specifications of 1995*, but was not listed as a superseded EI.

EI 95-047 will be shown as: Superseded by EB 05-001.

EI 98-037 *Bridge Deck Construction Specification Improvements – Implementation of Recommendations by the Bridge Deck Task Force*

Per Construction Division: This EI was superseded by EB 02-024 *2002 Standard Specifications for Construction and Materials*, but was not listed as a superseded EI.

EI 98-037 will be shown as: Superseded by EB 05-001.

EI 01-025 *Box-Beam Bursting Energy Absorbing Terminal (BEAT)*

Per Design Quality Assurance Bureau: This EI was superseded by EI 02-028 *Revisions to Standard Specifications, Type C End Assembly for Box Beam Median Barrier and Type III End Assembly for Box Beam Guide Rail*; EB 02-019 *Highway Design Manual Revision No. 40, Chapter 10 Roadside Design, Guide Rail, and Appurtenances*; and EB 02-024 *2002 Standard Specifications for Construction and Materials*, but was not listed as a superseded EI.

EI 01-025 will be shown as: Superseded by EB 05-001.

CONTACT:

Direct questions regarding this EB to Hal G. Rogers in the DQAB at (518) 457-5597 or e-mail hgrogers@dot.state.ny.us.