



To:  <b>SUPERSEDED BY EB 06-057</b> <b>EFFECTIVE 5/3/07</b>		New York State Department of Transportation <b>ENGINEERING</b> <b>BULLETIN</b>	<b>EB</b> <b>05-042</b>
<b>Title: REPLACEMENT PAGES 2, 3, AND 4 OF 12 FOR EI 05-028 SECTION 700 MATERIALS SPECIFICATIONS – REVISED TO COMPLY WITH NEW QUALITY ASSURANCE PROCEDURES</b>			
Distribution: <input checked="" type="checkbox"/> Manufacturers (18) <input type="checkbox"/> Surveyors (33) <input checked="" type="checkbox"/> Local Govt. (31) <input checked="" type="checkbox"/> Consultants (34) <input checked="" type="checkbox"/> Agencies (32) <input checked="" type="checkbox"/> Contractors (39)	Approved:   John E. Rondinaro, Director, Materials Bureau <u>22 AUG 05</u> Date		

**ADMINISTRATIVE INFORMATION:**

- **Effective date:** Effective upon signature.
- **Superseded issuances:** No issuances are superseded; however, replacement pages and revised shelf note amend EI 05-028.

**PURPOSE:**

The purpose of this EB is to issue replacement pages 2, 3, and 4 of 12 previously issued by EI 05-028 Section 700 Materials Specifications – Revised to Comply with New Quality Assurance Procedures.

**TECHNICAL INFORMATION:**

- **Actions by all units:** Obtain the revised shelf note which is included in EI 05-028 on the Department’s website.
- Two typographical errors have been identified in the shelf notes to EI 05-028. On page 2 of 12, above §704-04, should be lines “5-43” and on page 3 of 12, §704-09, Stone Blocks was deleted with no replacement. This item should not have been deleted.

**IMPLEMENTATION:** Existing copies of EI 05-028 should be discarded immediately and replaced with the EI on the Department’s website. EI 05-028 remains effective January 12, 2006.

**TRANSMITTED MATERIALS:** The revised shelf note is not attached to the EB. The full text of the revisions can be found on the Department website at [www.dot.state.ny.us](http://www.dot.state.ny.us). Select Site Index > E > Engineering Directives, Instructions, Bulletins and the EIB Program > Engineering Instructions > Issued in 2005 > EI 05-028.

**CONTACT:** For questions regarding this EB contact Kurt Matias of the Materials Bureau at 518-457-4586 or by e-mail at [kmatias@dot.state.ny.us](mailto:kmatias@dot.state.ny.us).