


Superseded by EI 85-31 Eff. 10/31/85

TO:	ENGINEERING INSTRUCTION		
	NEW YORK STATE DEPARTMENT OF TRANSPORTATION		
SUPERSEDED	SUBJECT: GUIDE RAIL IN THE CATSKILL PARK		
	Subject Code: 7.27-1-606		
Distribution:	<input checked="" type="checkbox"/> Main Office	<input checked="" type="checkbox"/> Regions	<input checked="" type="checkbox"/> Special
APPROVED:	 R. H. EDWARDS, Deputy Chief Engr., Fac. Des. Division		Code: EI 84-25
			Date: 5-4-84
			Supersedes:

As a result of discussions with the Catskill Council, Deputy Commissioner Carlson has established the following policy to improve the esthetics of highways in Catskill Park:

On construction contracts, only weathering steel will be specified for new guide rail installations within the boundaries of the Catskill Park. It will not be necessary to paint or replace existing guide rail just for esthetic purposes. However, if it is necessary to replace guide rail for other reasons, the replacement will be made with weathering steel.

The items below are approved pay items for the various weathering steel guide rail systems:

- 15606.1010 BOX BEAM GUIDE RAILING (Controlled Oxidizing)
- 15606.1110 BOX BEAM GUIDE RAILING (Shop Curved) (Controlled Oxidizing)
- 15606.1210 BOX BEAM MEDIAN BARRIER (Controlled Oxidizing)
- 15606.1310 BOX BEAM MEDIAN BARRIER (Shop Curved) (Controlled Oxidizing)
- 15606.1410 BOX BEAM GUIDE RAILING END ASSEMBLY (Controlled Oxidizing)
- 15606.1510 BOX BEAM MEDIAN BARRIER END ASSEMBLY, TYPE A (Controlled Oxidizing)
- 15606.1610 BOX BEAM MEDIAN BARRIER END ASSEMBLY, TYPE B (Controlled Oxidizing)
- 15606.1810 BOX BEAM CULVERT RAILING (Controlled Oxidizing)
- 15606.2010 CORRUGATED BEAM GUIDE RAILING (Controlled Oxidizing)
- 15606.2110 CORRUGATED BEAM MALL BARRIER (Controlled Oxidizing)
- 15606.2210 ANCHORAGE UNITS FOR CORRUGATED BEAM GUIDE RAILING (Controlled Oxidizing)
- 15606.2310 ANCHORAGE UNITS FOR CORRUGATED BEAM GUIDE RAILING (Driveway) (Controlled Oxidizing)
- 15606.2410 ANCHORAGE UNITS FOR CORRUGATED BEAM MALL BARRIER (Controlled Oxidizing)
- 15606.2510 SPECIAL ANCHORAGE UNITS FOR CORRUGATED BEAM MALL BARRIER (Controlled Oxidizing)
- 15606.8110 GUIDE RAIL TRANSITION CORRUGATED BEAM TO BOX BEAM (One or Two-Way Operation) (Controlled Oxidizing)
- 15606.8210 GUIDE RAIL TRANSITION BOX BEAM TO CORRUGATED BEAM (One-Way Only) (Controlled Oxidizing)

This policy will be in effect for all contracts let on or after August 1, 1984.